


## How to put on PPE (when all PPE items are needed)



### Step 1

- Identify hazards & manage risk. Gather the necessary PPE.
- Plan where to put on & take off PPE.
- Do you have a buddy? Mirror?
- Do you know how you will deal with waste?



### Step 2

- Put on a gown.



### Step 3a

- Put on face shield.


OR

### Step 3b

- Put on medical mask and eye protection (e.g. eye visor/goggles)




**Note:** If performing an aerosol-generating procedure (e.g. aspiration of respiratory tract, intubation, resuscitation, bronchoscopy, autopsy), a particulate respirator (e.g. US NIOSH-certified N95, EU FFP2, or equivalent respirator) should be used in combination with a face shield or an eye protection. Do user seal check if using a particulate respirator.



### Step 4

- Put on gloves (over cuff).

## How to take off PPE




### Step 1

- Avoid contamination of self, others & the environment
- Remove the most heavily contaminated items first


### Remove gloves & gown

- Peel off gown & gloves and roll inside, out
- Dispose gloves and gown safely



### Step 2



- Perform hand hygiene



### Step 3a

#### If wearing face shield:


- Remove face shield from behind
- Dispose of face shield safely



### Step 3b

#### If wearing eye protection and mask:

- Remove goggles from behind
- Put goggles in a separate container for reprocessing
- Remove mask from behind and dispose of safely



### Step 4

- Perform hand hygiene